Jonathan France - FD Janice,

I will not be able to attend the meeting, these are the questions/comments that we have.

- 1. Applicant needs to update the Vehicle Turning Plan to verify that fire department access is available in accordance with the State Fire Code (NFPA 1 Chapter 18). It would appear that the latest layout might not provide access around the building.
- 2. Based on initial review it would appear that 2 fire hydrants are necessary to meet the required fire flow demands as outlined in the State Fire Code (NFPA 1 Chapter 18). We would propose hydrants on opposing corners of the building with one closest to the sprinkler fire department connection.
- 3. In order to verify the adequacy of the water supply available at the site a hydrant flow test would be required. Applicant should work with a fire protection engineer and/or a sprinkler contractor to determine sprinkler demand requirements.
- 4. The Fire Department does not have a ladder truck at this time. We rely on mutual aid from Hopkinton or New London typically for a ladder truck. Depending on the type of call, staffing and call volumes a delay may occur from those towns providing Warner this resource if needed. This could have a negative impact depending on the emergency.

Thank you, Jon

Jonathan D. France Fire Chief Warner Fire Rescue 148 West Main Street Warner, NH 03278 Phone: (603) 748-4428